

Use your Browser
"Back" Button
to Go-Back



Kaiser Bill's

Tech Tip

Steering Problem - K-F Drag Link

The Drag Link on early 1951 Kaisers can cause steering interference with the oil pan when making a sharp left turn. If you are experiencing this problem you'll need a copy of Factory Advance Bulletin #46 dated July 11, 1950.

The Drag Link must be bent as shown in the bulletin to eliminate the problem or you can change to a later version oil pan. The oil pan was the problem.

- Kaiser Bill